

Summary Information On Underground Storage Tanks (USTs)

10/01/2015 - 09/30/2016

General Information

Total Number of UST Facilities: 3,017

Total Number of USTs: 8,161

Summary Information For Inspections

Number Of UST Facilities Inspected: 1073

Percent Compliance (Combined Measure): 58

Note: Inspections measure compliance with Significant Operational Compliance.

Summary Information For Releases

Number Of Confirmed UST Releases: 117

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	6	10.0	0	0.0	0	0.0	1	10.0	0	0.0	0	0.0	0	0.0	3	7.0
Piping	14	23.0	0	0.0	0	0.0	8	800.0	0	0.0	0	0.0	0	0.0	5	12.0
Dispenser	3	5.0	1	50.0	0	0.0	1	10.0	0	0.0	0	0.0	0	0.0	1	2.0
STP	4	7.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	4	10.0
Delivery Problem	1	2.0	1	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Other	1	2.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	50.0	0	0.0
Unknown	31	52.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	50.0	29	69.0
Totals	60	100	2	100	0	100	10	100	0	100	0	100	2	100	42	100

= number, % = percent of total number

For site specific information, please contact MDEQ Public Information Officer at 601-961-5118

Report Date: 11/16/2016